

Output Screen from Steam Trap Software

The screenshot displays the TrapManager software interface with several windows open:

- Trap 03062 Area (092) UTL-1092:** Shows current and previous inspection data.

Current		Previous	
Inspection Date:	2/24/2002	Inspection Date:	6/15/2000
Test Result:	BLOWING	Test Result:	BLOWING
Judgement Mode:	Automatic		
Leak Level:	15		
Steam Loss:	77.59 lb/hr	Steam Loss:	109.66 lb/hr
Monetary Loss:	2,719 \$/Year	Monetary Loss:	3,843 \$/Year
Surface Temp:	460 F		
- Trap 03064 Area (092) UTL-1092:** A form for entering C1, C2, C3, C4, and Comments.
- Trap 03061 Area (092) UTL-1092:** A form for entering operational parameters like Sat. Pressure, Back Pressure, Set Temp, Steam Cost, Priority, and Inspection Frequency.
- Trap 03062 Area (092) UTL-1092 (Main Table):** A table listing trap details.

Description	Operation	Other	Inspection
092 03052 FS310	NO CHECK		
092 03053 1011	LOW TEMP	2/17/2002	
092 03054 1011	GOOD	2/17/2002	
092 03055 1011	LOW TEMP	2/17/2002	
- Trap 03062 Area (092) UTL-1092 (Details):** Shows location (Tree at W stairs to boiler deck), manufacturer (ARMSTRONG), type (BUCKET), model (1011), and trap code (2843).



U.S. Department of Energy
Energy Efficiency
and Renewable Energy



Texas Industries of the Future